

2017年度 融雪システム稼働状況レポート(石川県金沢市)



2018.1.12 撮影



日	平均気温 (°C)	最深積雪 (cm)	降雪量合計 (cm)	平均風速 (m/s)
1/11	0.4	32	32	9.7
1/12	-0.7	14	46	4.1
1/13	0.1	24	62	4.8

